


Bird's eye view of the landslide of 25 Oct 2026 that claimed one life



Source: <https://www.nst.com.my/news/regional/2026/10/1563139/>



This Google Earth (GE) image of the area 3 months before the landslide shows area A was partly cleared of vegetation

Evidence from historical satellite images show that the slope immediately behind the houses along Lebuhr Rambai 13 have been unstable, and that ad-hoc measures had previously been taken to correct past slope failures.

30/10/2026



This Jan 2026 GE image shows that there was already a partial cementing of the slope in area A , indicating a slope failure would have happened there. Area B had been cemented over.



This Feb 2022 GE image shows bare surface left exposed in Area B when an earlier cement cover got worn down.



This Mar 2020 GE image shows Area B had previously been cemented over, indicating a slope failure would have happened there.



This Feb 2018 GE image shows blue plastic sheet covering Area B, indicating a slope failure would have happened there.